

Applicant: GAOMI LONGFEI SHOES CO.,LTD
INTERSECTION OF GAOMI PHOENIX
STREET AND WEST OUTER RINGROAD,
ONE KILOMETER NORTH EAST

Date: Feb 20, 2019

Attn: JOANNA

Sample Description:


Two (2) groups of submitted sample said to be:
(A) Three (3) pairs of Injection lace up safety ankle boots in Black.
(B) Two (2) pairs of Injection lace up safety ankle boots in Army Green.
Standard : Nch 2147/2.Of 93
Size : EUR 39, 41
Colour : A: QUEBEC 250-BLACK
 B: QUEBEC 670-ARMY GREEN
Ref. : A: QUEBEC 250
 B: QUEBEC MINERO
Date Received/Date Test Started : Feb. 18, 2019
Date Final Information Confirmed: --

Conclusion:

<u>Test Item</u>	<u>Result</u>
Electrical Insulation For Whole Shoe	Pass

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By:
For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch



Lin Lin
General Manager



Electrical Insulation For Whole Shoe (Nch 2147/2.Of 93)

(A)

Nch's Requirement

Without Disruptive Discharge To Ground Under The Alternating Current Of 14,000 Volts 50 Hz For 1 Minute With 1 Pair Of Tested Samples, Leakage Current:

Left: 0.11 mA
Right: 0.12 mA

*
*

(B)

Nch's Requirement

Without Disruptive Discharge To Ground Under The Alternating Current Of 14,000 Volts 50 Hz For 1 Minute With 1 Pair Of Tested Samples, Leakage Current:

Left: 0.17 mA
Right: 0.15 mA

*
*

Remark: * = The Isolated Safety Footwear Has To Be Resistant To An Alternating Current Application Of 14,000 Volts And A Nominal Frequency Of 50 Hz For 1 Minute, Leakage Current: ≤ 5.0 mA.



End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.